


Assembly Instructions

Up-dux® Ceiling Vent Top'R™ Model DL-101-T

Since the two major components of the Up-dux® are packaged telescoped together, step one of assembly requires sliding the inner section up and out of the lower sleeve section.



Next, with the lower sleeve component on a table or other level surface and with the labeled side facing you, hang each of the four cradle brackets in position on the top edge of each sleeve panel, as shown above. Be sure to position all the brackets so that their center slotted holes line up with those of the supporting sleeve panels.

Now, carefully place upper component, with label facing you, in position resting on the inside flanges of cradle brackets. Holes of all components on all four sides should now be aligned and assembly can be completed by fastening the upper and lower product sections to each other with four 1/4" sheet metal screws which are included with the hardware packet.